Oil Field Environmental Incident Summary

Incident: 20161012164607 Date/Time of Notice: 10/12/2016 16:46 Responsible Party: CORNERSTONE NATURAL RESOURCES LLC CORNERSTONE NATURAL RESOURCES LLC Well Name: STATE 15-33 Field Name: PORTAL Well File #: 17598 Date Incident: 10/5/2016 Time Incident: 12:00 Facility ID Number: **BURKE** Twp: 164 **Rna**: 91 Sec: 33 Qtr: County: Location Description: Submitted By: Richard Arp Received By: Contact Person: Richard Arp 1401 17TH ST, STE 1175 DENVER, CO 80265 General Land Use: Well/Facility Site Affected Medium: Topsoil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Equipment Failure Release Contained in Dike: Unknown Reported to NRC: No Units Spilled Recovered Units Followup **Units** Oil **Brine** Other **Barrels Barrels Description of Other Released Contaminant:** Until soil testing is done we are unsure of the non-growth and alkalin presences. Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None Areal Extent:

Potential Environmental Impacts:

Soil contamination

Action Taken or Planned:

Unknown till testing is back.

Wastes Disposal Location: NA

Agencies Involved:

Updates

Date: 10/13/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, it was unknown if the release due to equipment failure was contained. Description of product released is also unknown. Spill also reported 8 days after release. Further follow-up needed.

Date: 11/2/2016 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 4:03, 11/2/2016.

Dike around well is large enough to handle large releases, and there are no signs of impacts to the environment around the well pad. Analysis of water in the ditch indicates chlorides around 160 parts per million (ppm), which is elevated above natural rainwater but below the water quality guidelines.

Contact company to see if any samples were taken regarding the presence of an alkaline area.

More follow-up is necessary.